ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 13 | Mallasandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0060, W0010, W0154 | NA | Govt school |
| **Segment No.** | **Total Length (m)** | |
| 13/S-W0232/S075918 | 140.0 | |

Segment Details

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 30.0 | 77.515659 | 13.071638 | 77.516622 | 13.071343 | W0234 | DE |
| 2 | 50.0 | 77.515487 | 13.071410 | 77.515555 | 13.070946 | W0234 | DE |
| 3 | 30.0 | 77.515930 | 13.071834 | 77.516815 | 13.071400 | W0234 | DE |

### Work Details

History of Road / Lane / Circles

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvement and asphalting to mallasandra main road from govt school to anjaneya swamy temple road | 25.00 | 2013 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2012 – 2013 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not Tender | ROAD | 013-13-000037 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/DD/WO/447/2012-2013 | 08/03/2017 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 08/03/2013 | 07/07/2013 | |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| KRIDL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9743188999 | | |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಿವಾಜಿನಗರ ಉಪವಿಭಾಗ, ಪಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Nagabhushan |

Date of Inspection

Remarks -

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Segment End |  | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | VIJAY KUMAR | 05/06/2017 | 05/07/2017 | COMPLETED |
| EE | SHESHADRI | 05/06/2017 | 05/07/2017 | COMPLETED |
| AEE | JAYALINGAPPA | 05/06/2017 | 05/07/2017 | COMPLETED |
| AE | NAGABHUSHAN | 05/06/2017 | 05/07/2017 | COMPLETED |
| AE | NAGABHUSHAN | 05/06/2017 | 05/07/2017 | COMPLETED |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Zone: DASARAHALLI Ward No: 13 Ward Name: Mallasandra Street ID: